

# MY SLOT NOTES

RESULT = Robert E Sult


For the best reSULT conSULT SULT

## *APS Model MCP8011*

No 13 Volts

No 25 Volts

Main connector – cold solder joint



Found 4 with the same problem



*Robert E. Sult AOS*

Slot Technician / Bench Technician

Associate in Occupational Studies Electronic Technology