

# MY SLOT NOTES

RESULT = Robert E Sult

For the best reSULT conSULT SULT

Subject: Bally Power supply

*LFZVC65SG24S52*

Here you will find some of my notes:

In no way should they be used as a (SHORT CUT)

Or replacement for the correct trouble-shooting procedures.

If nothing else, if you are stuck on a problem, the information here may give you another area to look at.

Tagged Bad, during testing found output at 21.8 vdc



Replaced C2 100uF 25 volts (Output now 24.1 vdc)





*Robert E. Sult AOS*

**Slot Technician / Bench Technician**

Associate in Occupational Studies Electronic Technology