

MY SLOT NOTES

RESULT = Robert E Sult

For the best reSULT conSULT SULT

IGT Power supply 40009001



I guess I should assume this is too old to fix. As it I have found the (it has a blown fuse) also found that CR17 – CR16 – Q2 A3 Q16 Q8 and Q7 was all shorted. Needs to be replaced.

If I can't get a \$1.38 diode for the PAS MCP8011 which is a newer version of the Condor, then for sure they will not the parts needed to fix this one – Hate to say it (but its trash)

