

MY SLOT NOTES

RESULT = Robert E Sult
For the best reSULT consULT SULT

JCM power supply



This Page will continue to be updated.

So Far, the only problem I have seen was with C13 [82 uF 200 v Cap]

it could of started with a cold solder joint - found C13 loose

I removed the loose cap, and put in a new one. Works fine.



12.25 VDC

+
-

