

MY SLOT NOTES

RESULT = Robert E Sult
For the best reSULT conSULT SULT

Kortek 1703 1903 BLACK OUTS

Check - replace Horizontal output transistor - AKA (HOT), Q402
BU2520DF - Cross-reference part NTE2352 work well.

I'm now using BU2520DX

You can test Q402 by placing your meter on Diode check, then check for shorts between the center leg and the outside leg of the BU2520DF

Note: If you change Q402

Then change C421 10Uf 50v cap.