

# MY SLOT NOTES


RESULT = Robert E Sult  
For the best reSULT conSULT SULT

Kortek 1703 1903 Dim & Sync



Just to get this Photo, I had to turn off the shop lights - This monitor was very dim.

Dim & Sync Problem



Most of the time I would say C123 470uF 16v cap.

It has been the problem on the last 35 monitors. I would also replace C126 470uF 16v.



Some would also replace C408 the 22uF 160v cap.

