

MY SLOT NOTES

RESULT = Robert E Sult

For the best reSULT conSULT SULT

Kortek 1703 1903 Vertical Deflection

Vertical Deflection is working just not adjusting to the fill the screen.

Found C506 bad - 47uF reading .2uF

Vert Deflection compressed / rollover

Bottom part looked fine

Found C119 & C122 bad 1000uF 35v