

MY SLOT NOTES

RESULT = Robert E Sult
For the best reSULT conSULT SULT

Kortek 1703 1903

POWER PROBLEMS

- could be C107 47uF & C108 1uf 50v

Note:

C108 connects to pin 5 of the IC101

C107 connects to pin 3 of IC101

IC101 is a KA2S0880 - A SMPS with minimal external component. The SPS consist of high voltage sense FET - and current mode PWM IC included control IC feature a TR-limmed oscillator under voltage lock out.

Some times - (very few times I have had to replace IC101 - KA2S0880)