

# MY SLOT NOTES

**RESULT = Robert E Sult**  
**For the best reSULT conSULT SULT**

Kortek 1703 1903

DARK Vertical Strip on left side

Replace C408 22uf 160v

I would also change C407 470uF 25v

and C406 470uF 25v