

MY SLOT NOTES

RESULT = Robert E Sult
For the best reSULT conSULT SULT

Kortek Monitor KT1703N 1903

Sides of display jumping

Jitters - Picture Jumping - Pulsing

Replace C408 22uF 160v cap most likely going bad or is bad

Also change C407 470uF 25v

and C406 470uF 25v