



# MY SLOT NOTES

RESULT = Robert E Sult

For the best reSULT conSULT SULT


## Kortek Power Supply KT-PS60PF

Problem: Blacked out LCD Monitor



Replaced C835 & C837 1000 uF 25v / C834 470 uF 16v /

C826 & C828 47 uF 50v / C836 C825 1 uF 50v



*Robert E. Sult AOS*

**Slot Technician / Bench Technician**

Associate in Occupational Studies Electronic Technology