

MY SLOT NOTES

RESULT = Robert E Sult

For the best reSULT consULT SULT


APS

Model MCP8011

No 13 Volts

No 25 Volts

Main connector – cold solder joint



Found 4 with the same problem
