

MY SLOT NOTES

RESULT = Robert E Sult
For the best reSULT conSULT SULT

IGT Poker Game (Bar top)

So far there have been many different

Games that had this Problem.

Constant Door Open.

They Found that the Hopper Optic was shorted. And since; The Machine calls for a Slow blow Fuse. It will take out the Diode on the Board.

CR26 1N4002



